## CHANGES IN BULLETIN 141 (ISSUE 3) DESCRIPTION AND ADJUSTMENTS TRANSMITTER-DISTRIBUTOR

The following changes apply to the Model 14 Transmitter-Distributor equipped with the 77079 tape stop assembly.

## Page 10

## Tight-Tape-Stop or Auto-Stop Mechanism

Add the following note below "a".

Note: For installations where the transmitterdistributor operates at a faster speed
than the unit preparing the tape, adjust
as follows:

When the contacts are held closed by the contact operating post the bottom of the tight-tape stop lever should be approximately one inch below the normal horizontal position and the tight tape stop shaft should protrude approximately 1/16" beyond the clamp (Fig. 24A). Make the adjustments simultaneously by positioning the clamp.